


BUILDING SAFETY CERTIFICATE

No.: 39.1.....

Dated: 27/3/2023

Considering the request of Principle, **Ojas Global School**, Ward No.04 Baihar Road Devtola District-Balaghat (M.P.) The Building(Ground+First+second Floor) was inspected by undersigned alongwith Praveen kumar Sub Engineer & School Staff on date 16/03/2023. It was found from visual inspection that the Present Condition of the Building is satisfactory and the Building seem to be safe for the purpose of running the School. So, The Certificate regarding the Building safety is hereby issued which will be valid for **One Year up to 15/03/2024**.

Issued On 16/03/2023 at Balaghat by Sub Divisional Officer P.W.D. Sub Division No.01 Balaghat(M.P.)


Sub Engineer

P.W.D. (B&R)sub division no.01

Balaghat(M.P.)

Signature With Seal:


Sub Divisional Officer
P.W.D. Sub Division No.01

~~Balaghat (M.P.)~~
Designation : Sub Divisional Officer

P.W.D.(B&R)sub Division no,01


Balaghat(M.P.)

Endst No..39.2.....

Date- 27/3/2023

Copy of above is forwarded to the following for information and necessary action:-

1. The Principle of Ojas Global School ,Ward No.04 Baihar Road Devtola Balaghat (M.P.)
2. The Executive Engineer P.W.D.(B&R) Division No.01 Balaghat (M.P.) for Information & necessary action,Please.


Sub Divisional Officer
P.W.D. Sub Division No.1
~~Balaghat (M.P.)~~
Sub Divisional Officer

P.W.D. (B&R) Sub Division No.01

Balaghat (M.P.)